

EXHIBIT 13

Photo Sheet

CSAA Insurance Group
P.O. Box 2453
Oakland, CA 94623
(800) 207-3618 - Phone
(877) 548-1610 - Fax

Insured KYLE GOINS
Claim # 1001-80-2138
Policy # HO33579457



47-Left elevation

Date Taken: 12/11/2016

Taken By: Shane Haar

No damage found to the window screen



48-Left elevation

Date Taken: 12/11/2016


Taken By: Shane Haar

Member stated the wind pulled away the gutter.

Photo Sheet

CSAA Insurance Group
P.O. Box 2453
Oakland, CA 94623
(800) 207-3618 - Phone
(877) 548-1610 - Fax

Insured: KYLE GOINS
Claim #: 1001-80-2138
Policy #: HO33579457



4-Office

Date Taken: 12/11/2016

Taken By: Shane Haar

Member stated water was leaking out of the crown molding. Point of entry is from the roof where the exhaust skirt was blown up by the winds. No water stains could be observed.



5-Office

Date Taken: 12/11/2016

Taken By: Shane Haar

Overview

Photo Sheet

58


12/11/2016

CSAA_GOINS 0077

Photo Sheet

CSAA Insurance Group
P.O. Box 2453
Oakland, CA 94623
(800) 207-3618 - Phone
(877) 548-1610 - Fax

Insured: KYLE GOINS
Claim #: 1001-80-2138
Policy #: HO33579457



41-Fence

Date Taken: 12/11/2016

Taken By: Shane Haar

Left run: No spatter marks found



49-Fence

Date Taken: 12/11/2016

Taken By: Shane Haar

Front left: Member stated the wind blew off his gate